



Copyright

Copyright© 2021 NetComm Wireless Limited. All rights reserved.

Copyright© 2021 Vodafone Group Plc. All rights reserved.

The information contained herein is proprietary to NetComm Wireless and Vodafone. No part of this document may be translated, transcribed, reproduced, in any form, or by any means without prior written consent of NetComm Wireless and Vodafone.

Trademarks and registered trademarks are the property of NetComm Wireless Limited or Vodafone Group or their respective owners. Specifications are subject to change without notice. Any images shown may vary slightly from the actual product.



Note – This document is subject to change without notice.

Document history

Ver.	Document Description	Date
1.0	Initial document release	27 th August 2018
1.1	Updated for v2.0.83.0	27th February 2019
1.2	Updated for v2.0.90.0	5 th August 2019
1.3	Updated for v2.0.98.0	15 th November 2019
1.4	Updated for v2.1.10.0	4 th February 2021

FR01034 v1.4

Release information

ltem	Details
Product code	NWL-221 / NWL-222 / NWL-224
Router firmware version	2.1.10.0
Firmware file name	vdf_nwl220_2.1.10.0-signed.cdi
	MD5: 885DCEA70B1C22C6A171A853B2FA66EB
Firmware file size	67.3 MB
Date	4 th February 2021

v2.1.10.0

New features

- Data Profiles now support IPv6 and IPv4v6 PDP types
- Added an Intrusion Prevention System (IPS) firewall feature
- Added Serial port data status feature
- Added 'Site and location' feature
- Added a new set of LwM2M objects to the LwM2M client

Enhancements

- Fixed a LwM2M Queue mode update issue (TT#37761)
- Fixed an issue with sending PDP credentials (TT#39672)
- Improved the LwM2M client's functionality (TT#40782,40810,40811)
- Fixed an issue with "system.time.source" rdb variable reporting a blank value for network time source (TT#41365)
- Updated the PLMN list (TT#41534)
- Security enhancements (TT#s 41694, 40777, 40778, 39715)
- Cosmetic enhancements (TT#41428)

v2.0.98.0

Enhancements

- Improved the overall security of the device (TT #25134, TT #25137, TT #39029)
- Fixed a problem with the Ethernet port not connecting at 10Mbps (TT#39027)
- Added PADD functionality (TT#38773)
- Fixed an issue with LwM2M ID not being persistent (TT#38261)
- Cosmetic enhancements to web interface (TT# 24917, TT#39165, TT# 25194, TT# 24162, TT# 24165)
- Improved network and band selection behaviour (TT# 25671, TT# 25742, TT# 25190, TT# 25079, TT# 24166,
 TT# 24275)
- Added a 4G RSRP threshold field to the SIM Failover's *Switch from External /Internal SIM On Weak Signal* option. (TT# 25189)
- Improved Recovery mode functionality (TT# 24913, TT# 24915)
- Fixed issue where OTG external storage was not found. (TT# 24921)
- Added GEA1/ & 4 Ciphering algorithm's module command to firmware. (TT# 25000)

v2.0.90.0

Enhancements

- Improved the overall security of the device (TT# 25138)
- Added a unique default web interface password specific to each device (TT# 25139)
- Cosmetic enhancements to web interface (TT# 38594, 38611)

v2.0.83.0

Enhancements

- Improved network and band selection behaviour. (TT# 24918, TT# 25670)
- Cosmetic enhancements to web interface (TT# 25764)
- Special characters can be used in special APNs. (TT# 24223)